

One Green Ridge Road
Pittsford, New York 14534
April 26, 1986

Mr. James R. Papero
Senior Forester, Region 5
Ray Brook, New York 12977-0096

SUBJ: Water level of Eagle Lake

Dear Mr. Papero:

This is in further reference to my letter to you of December 11, 1985, and yours of January, 3, 1986.


As I told you I would, I tried to locate the pin in the rock in January when I was there. As suspected, this was a futile exercise.

However I was there yesterday, did locate the pin, and measured the water level above it. The lake was 9-1/4" above the center point of the pin. Graham Davis was with me and can help you locate the pin in the future.

As I mentioned in my previous letter, the original agreement was that the lake level should be at the level of the pin, plus or minus 4 inches. This means that at present Eagle Lake is 5-1/4 inches above the maximum to which the people on the lake have built their houses, docks and boat houses.

I trust that something can be done to rectify this situation.

Sincerely,



Robert C. Stevens

cc: George W. Conklin
Graham R. Davis
Mrs. Robert W. Emrich ← THIS COPY FOR →
Dr. Joseph R. Kane
Herbert Lamb, CRFS VI