Rensselaer

DARRIN FRESH WATER INSTITUTE

Sandra A. Nierzwicki-Bauer, Director

Richard F. Bopp Associate Director of Hudson River Program

Charles W. Boylen Associate Director of Environmental Assessment Programs

Report of Analysis LAB ID # 10719

Eagle Lake Bacterial Samples Date collected: September 4, 2012

Date analyzed: September 4, 2012 Collector: Rin Fraize

Sample =	Location	Time Collected	Time Analyzed	Total Coliform (#colonies/100 ml)	Fecal Coliform (#colonies/100 ml)
12-413	North	9:15	13:30	4	I
12-414	South	9:15	13:35	3	2
12-415	West Fox Island	9:15	13:40	3	1
12-416	Ti Bay	9:15	13:45	6	1

Results submitted by: Tiffini Burlingame

Total Coliform: Membrane Filter with LES Endo Agar, 9222 A,B,C (NELAC Certified) Fecal Coliform: Membrane Filter with LES Endo Agar, 9222 D (NELAC Certified) Fecal Streptococci - Membrane Filtration with KF Strep Agar, 9230 A,C (not NELAC certified) 2: refers to count with high non-target bacterial growth



Adirondack Field Station at Bolton Landing 5060 Lake Shore Drive | Bolton Landing, New York 12814-4317 Telephone (518) 644-3541 | Fax (518) 644-3640 Rensselaer Polytechnic Institute | 110 8th Street | Troy, NY 12180-3590 USA Telephone (518) 276-2359 | dfwi@rpi.edu | http://www.rpi.edu/dept/dfwi



Rensselaer

DARRIN FRESH WATER INSTITUTE

Sandra A. Nierzwicki-Bauer, Director

Date:

September 12, 2012

ELPOI PO Box 287 Ticonderoga, NY 12883

Sample #: 12-413 to 12-416

BILL FOR LABORATORY SERVICES

4	Total Coliform Bacterial Analysis @ \$15.00 ea.	\$60.00
	E. coli Enumeration Analysis @ \$20.00 ea.	\$0.00
4	Fecal Coliform Bacterial Analysis @ \$15.00 ea.	\$60.00
	Fecal Streptococci Bacterial Analysis @ \$15.00 ea.	\$0.00
	Standard Plate Count Bacterial Analysis @ \$15.00 ea.	\$0.00
	E. coli (qualitative) Bacterial Analysis @ \$10.00 ea.	\$0.00
	TOTAL LABORATORY FEES	120.00

Please make check payable to:Darrin Fresh Water InstitutePlease reference sample number12-413 to 12-416on checkMail Payment To:Darrin Freshwater InstituteAttn: L. Ahrens5060 Lakeshore DriveBolton Landing, NY 12814

Page 1 of 1



Lab ID: 10719

Revision No.1.1

Adirondack Field Station at Bolton Landing 5060 Lake Shore Drive | Bolton Landing, New York 12814-4317 Telephone (518) 644-3541 | Fax (518) 644-3640 Rensselaer Polytechnic Institute | 110 8th Street | Troy, NY 12180-3590 USA Telephone (518) 276-2359 | dfwi@rpi.edu | http://www.rpi.edu/dept/dfwi



Richard F. Bopp Associate Director of Hudson River Program

Charles W. Boylen Associate Director of Environmental Assessment Programs

Total

Rensselaer

DARRIN FRESH WATER INSTITUTE

Sandra A. Nierzwicki-Bauer, Director

Richard F. Bopp Associate Director of Hudson River Program

Charles W. Boylen Associate Director of Environmental Assessment Programs

Eagle Lake Property Owners P.O. Box 287 Ticonderoga, NY 12883

January 23, 2013

Re: Outstanding Payment

To Whom it May Concern,

In reviewing fiscal year 2012 accounts, it has come to our attention that we have not received payment for the water tests (Samples # 12-413 to -416) that we completed for you. Please find enclosed a copy of the original bill. If you believe payment has been sent to us, please contact us. Otherwise, please remit payment at your earliest convenience.

Sincerely,

Loui Alu

Laurie Ahrens Research Associate



Adirondack Field Station at Bolton Landing 5060 Lake Shore Drive | Bolton Landing, New York 12814-4317 Telephone (518) 644-3541 | Fax (518) 644-3640 Rensselaer Polytechnic Institute | 110 8th Street | Troy, NY 12180-3590 USA Telephone (518) 276-2359 | dfwi@rpi.edu | http://www.rpi.edu/dept/dfwi

